

**national
diagnostics**



- ◆ **Environmental Wipe Testing**
- ◆ **Surface and Equipment Decontamination**


Protocols for the use of National Diagnostics

Nuc-Wipes™ and **Nuclear™**

NUC-WIPES (NW-300)




Nuc-Wipes are dissolvable pads which assure superior environmental wipe tests. Nuc-Wipes are completely soluble in any scintillation solution, and because Nuc-Wipes dissolve completely, no emitted beta ray can be hindered or absorbed by an undissolved portion of the wipe. Nuc-Wipes allow full 4 π counting efficiencies, thereby eliminating the possibility of lost counts due to absorption of beta rays by the filter itself.



Intact filters used in wipe tests leads to inaccurate, erratic results. Beta rays originating from particles on intact filters are attenuated and absorbed by the filter. Furthermore, depending on the relative affinity of the material for the solution, as material leaves the filter, the change over time, giving results that are not reproducible.

Because Nuc-Wipes dissolve in scintillation fluid, there is no intact filter to absorb or attenuate beta emissions. 4 π counting efficiency is achieved. Reliability of

results is improved, thereby improving safety.



OVERVIEW OF ENVIRONMENTAL WIPE TESTING

Environmental wipe testing is an integral part of standard radiation monitoring protocols. In contrast to direct monitoring with devices such as a Geiger counter, wipe testing is an indirect survey method. Contamination is detected by wiping the surface with a pad, such as Nuc-Wipe from National Diagnostics. The amount of radiation present on the pad, and indirectly the degree of contamination of the surface, is determined by measurement by liquid scintillation counting. Typically, any area or item with radioactive contamination three times background is isolated and decontaminated. Test results are typically recorded in a logbook at a minimum of once every two weeks if work with radioactivity is routine. In the case of infrequent work, wipe tests should be performed after each use of radioactive materials.


WIPE TEST PROTOCOL

The following protocol is intended as a helpful resource. Your Radiation Safety Office may require special procedures not included in this method.

1. Create a detailed floor plan of the laboratory of the work area and equipment for monitoring including bench tops, protective bench paper, shields, pipetmen, door handles, clothing, etc. as well as all devices or apparatus used in radionuclide work.
2. Mark locations to be tested on a dated copy of the floor plan. Use a simple alphanumeric code to uniquely identify each location on the map.
3. Using a system of labels corresponding to your alphanumeric code, label a 20ml scintillation vial to correspond to each wipe location.

WIPE TEST PROTOCOL (continued)

4. Label an additional vial for use for the background count.
5. Use a Nuc-Wipe moistened with 65% – 75% ethanol to wipe each area to be tested. Wipe an area approximately of 100 sq. cm applying moderate pressure. Because consistency in wipe technique is essential for reliable results, we recommend wiping with the same, easily repeatable pattern at each location.



6. Place the wipe in the corresponding labelled scintillation vial and allow to air dry. Repeat process for each location to be monitored.
7. Place a clean Nuc-Wipe in vial labelled for background determination.
8. Add 10ml of emulsifying scintillation fluid to each vial. (For this application we recommend National Diagnostics Ecoscint H (LS-275), which combines

high counting efficiency, biodegradability, and the capability to emulsify or dissolve both polar and nonpolar residues.) Agitate for 5 minutes or until Nuc-Wipes have completely dissolved.

9. Measure the radioactivity on each wipe using a liquid scintillation counter. Record the results in the manner preferred by your Radiation Safety Office.
10. Decontaminate any areas that are determined to be contaminated with radioactivity*, then rewipe. Decontaminate the area(s) until the measured levels are below guidelines. (see the following pages for decontamination methods).

**Your Radiation Safety Office will provide the guidelines regarding the threshold of contamination in your work area. A common standard is to consider any location that measures greater than 3 times background to be contaminated.*

NUCLEAN (NC-200)



- Safe and Effective Radioactive Decontamination
- Superior Cleaner
- Biodegradable
- pH Neutral
- Won't Damage Metal Instruments

Nuclear is a concentrated, economical and highly efficient solution for safe and fast removal of radioactivity from laboratory glassware, equipment and laboratory surfaces. It is also a superior general laboratory cleaner and degreaser.

Nuclear is biodegradable and mild to the skin when diluted 1:50. Nuclear is not only more effective than chromic acid but is safer to use as well. Quart containers are supplied with a spray-head.

In normal use, Nuclear is diluted 1:50 with water, and the glassware allowed to soak overnight and rinsed clean with distilled water. Faster decontamination is effected by increasing the concentration to 1:20 and elevating the temperature. Agitation will greatly accelerate the process.

For surface decontamination, such as lab benches and tops, Nuclear can be used diluted or undiluted, depending on the difficulty of decontamination.

SURFACE DECONTAMINATION

1. Wipe from the outside (to avoid spreading contaminants) with dilute (20:1) Nuclear. Rinse with water. Resurvey.
2. If contamination persists, repeat with concentrated Nuclear (wear double gloves).
3. If contamination continues to persist, label areas using radioactive label tape, and notify the Radiation Safety Office.
4. Dispose of all contaminated materials (such as paper towels, gloves, etc.) in the appropriate radioactive waste containers.
5. Monitor personal effects such as shoes and clothing before leaving the area.

EQUIPMENT DECONTAMINATION

1. If possible, soak in dilute 50:1 Nuclear overnight in a bin labeled for radioactive materials. Rinse with water and resurvey.
2. If soaking is not possible, wipe from the outside (to avoid spreading contaminants) with dilute (20:1) Nuclear. Rinse with water. Resurvey.
3. If contamination persists, repeat with concentrated Nuclear (wear double gloves).

Ordering Information

Nuc-Wipes

NW-300

Box of 100 wipes

Nuclear

NC-200

1 quart
1 gallon

Ecoscint H

LS-275

4 liter
20 liter
55 gallon

UNITED STATES

National Diagnostics U.S.A.
305 Patton Drive
Atlanta, Georgia 30336

Toll Free: 800-526-3867
Phone: 404-699-2121
Fax: 404-699-2077
Email: info@nationaldiagnostics.com
Web: www.nationaldiagnostics.com

EUROPE

National Diagnostics (UK) Ltd
Unit 4 Fleet Business Park
Itlings Lane, Hessle
East Riding of Yorkshire HU1 39LX
England

Phone: 44 (0) 1482 646020
44 (0) 1482 646022
Fax: 44 (0) 1482 646013
Email: customer@nduk.clara.net
Web: www.nationaldiagnostics.com

**national
diagnostics**